

North Division Street Hydro Facility Rehab Phase 2 - Construction photos
Hydro Project P-8949 - NY
NATDAM ID No. NY 11430



The crew works on cleaning out debris from the lower pit (8-07-17).



The crew has begun installing water board (8-08-17).



Electrical work has begun along the south wall (8-09-17).



Rebar has been installed in the lower pit (8-10-17).

North Division Street Hydro Facility Rehab Phase 2 - Construction photos
Hydro Project P-8949 - NY
NATDAM ID No. NY 11430



Concrete has been placed in both the trench and the Sonotubes (8-11-17).



The Carpenters are working on installing the formwork in the lower pit (8-12-17).